CORNER RECORD (SEARCH) Tract or Survey No. _____ Cor. No. J-9

#820

No. _____ R.D. Hebo County TILLAMOOK

.5 S R. 9W N.F. SIUSLAW State C.Re.

Id. Will.

ER DIAGRAM



17 16 9

DESCRIBE CORNER MONUMENT FOUND

CAUDLE 1880 SETS A POST AND MARKED:
A 40" FIR, N.45°E., 20 LKS. (GLO)
A 30" FIR, S.30°E., 166 LKS.
A 24" FIR, N.50°W., 90 LKS.

TILLA. CO. SURVEYOR 1895 MARKED:
A 40" FIR, N.20°W, 20 LKS.
A 48" FIR, S.59°E., 103 LKS.

I FOUND A 48" SNAG, S.57°E (NOT 59°) 103 LKS. WITH FAINT SCRIBE MKS. "T5S S16 BT."
FOUND A SNAG 40", N.10°W. (NOT 20°) 20 LKS. WITH MKS. ROTTED OFF. THIS FITS 1895 TILLA. CO. SURVEYOR DESCRIPTION.
FOUND A ½" PIPE N.60°W. 7 FT. FROM THE ABOVE POINT.

Q IDENTIFICATION DATA

No. _____
At. _____
Ident. _____
By _____ Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FROM THE ABOVEMENTIONED PIPE ARE 2 MKD. TREES. (ABOUT 30 FT.)
10" FIR, SNAG, N.45°W., 40 FT. WITH MARKS "BTS"
14" FIR, S.45°W., 25 FT. WITH MARKS "BT" NO RECORD OF THESE BTS

Leonard Whitmore, Forestry tech 2-27-68

COORDINATE POSITION D

_____ Zone _____

Signature	Title	Division	Headquarters	Date	7100-52
Leonard Whitmore	Forestry tech	[illegible]	Hebo	2-27-68	REV. 65

TILLAMOOK COUNTY REWITNESS

N.W. SE
COR. _____ T _____ R _____ W., WM.
S. E. DLC.# _____

HISTORICAL:

CONDITION FOUND:

LEONARD WHITMORE			
[illegible]			
[illegible]			

COMMENTS: