


File No. 12-11 Survey No. 823
 T. 5S R. 9W R.D. Hebo County Tillamook
 Merid. Willamette N.F. Siuslaw State Oregon



DESCRIBE CORNER MONUMENT FOUND
 Found a crumbly stone 8x8x6 with smaller pieces underneath. A galvanized steel post and 2"x2" Vine Maple post beside stone. Approximately 14 feet N12E was a 26" fir with X and location poster giving location of stone as approximately 1/4 corner.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 No bearing trees found.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO, HOW TO REACH CORNER
 Drive north on Hwy 22 to section Line Crossing of section 9 and 16. Follow fence line east of approx. 15 chains to edge of green timber.

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____
 Signature _____

Title ORLS Division 650 Headquarters _____ Date 1/70 7100-52 REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 Set a 2"x30" iron pipe with brass cap mkd
 T5S R9W
 1/4 9 Set steel post and wood post beside cap.
 16
 1969--650

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
 fir brs. S70E 49.4 ft. (slope) Set steel fence post 3 feet north of
 scribed 1/4 S16 BT 650 cap with F.S. boundary and attention
 signs facing west; placed BT tags and
 26" fir brs. N13W 13.9 ft. painted red band on BT's.
 scribed 1/4 S9 BT

Work Done By T.O. McCullough Title Surveyor Date 1969 State Registration No. ORLS 650
 or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS
 Witness to the above corner: R.L. Bryant