

INDEX FOREST SERVICE

CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. # 821 Cor. No. L-5

File No. T 5S R. 9W R.D. HEBO County TILLA. State ORE.

Merid. WILL. N.F. SIUSLAW

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND GLO 1880 SET 10x7x5, ROCK WITH STONE MOUND.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND AT CORNER POINT I FOUND A MOUND OF ROCKS CONSISTING OF 10 STONES. NO IDENTIFICATION MARKS CAN BE FOUND, THOUGH THE ROCKS FIT TOGETHER AS IF MAN MADE.

PHOTO IDENTIFICATION DATA

Photo No. E1J-9-191

Filed At. _____

Object Ident. _____

Ident. By _____ Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____ Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER THE CENTER STONE MEASURES 10x9x5 SET 3x3x40 POST ALONGSIDE STONE. REFERENCE A 34" SPRUCE, N. 3° W., 93 FT. A 50" SNAG, S. 46° E., 50 FT. BLAZE X, PAINT RED ON FACES OF REFERENCES.

ATTACH LOCAL POSTERS. Leonard Whitmore

Signature Leonard Whitmore Title Forestry Tech Div. Timber Headquarters Hebo Date 4-15-69 7100-52 (3/68)

REWITNESS

I SET _____

"x" "x" "Post N.W. _____ feet

" Hat Section S. E.

NEW ACCESSORY:

COMMENTS: _____

IN THE PRESENCE OF: _____

DATE: _____

PHOTO# _____

LIFTWOOD CORNER NUMBER _____ TITLE _____

* County corner tag affixed.