

Index File No. <b>R-3</b>	CORNER RECORD (SEARCH) <i>Brasscapped</i> BLM 1972	Tract or Survey No. _____	Cor. No. <b>R-3</b>
T <b>5 S</b> R. <b>9 L R. D.</b>	<b>Hebo</b> County <b>TILLA.</b>	<b>#828</b>	
Merid. <b>Will.</b> N.F. <b>SILSLAW</b> State <b>ORE.</b>			
CORNER DIAGRAM 	DESCRIBE CORNER MONUMENT FOUND <b>CAUDLE 1880 SET A POST AND MARKED: (GLD)</b> <b>A 30" SNA9, S. 45° E., 47 LKS.</b> <b>A 40" SNA9, N. 68° W., 10 LKS.</b>		
PHOTO IDENTIFICATION DATA Photo No. _____ Filed At. _____ Object Ident. _____ Ident. By _____ Signature _____	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND <b>M. WHITMORE 1957 FOUND A 30" SNA9, S. 45° E., 47 LKS. WITH MKS. 1/4 SBT. SHOWING.</b> <b>He FOUND 40" SNA9, N. 68° W., 10 LKS. WITH MARKS ROTTED OFF.</b> <b>He MARKED 2 BT'S:</b> <b>A 18" ALDER, S. 84° W., 64 1/2 FT. BARK SCRIBED 1/4 S 30 BT (IT IS NOW A SAWED OFF STUMP WITH MARKS SHOWING).</b>		
PLANE COORDINATE POSITION State _____ Zone _____ X _____ Y _____ Estab. By _____ Agency _____	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER <b>A 14" ALDER, N. 74° W., 71 FT. BARK SCRIBED 1/4 S 19 BT. (NOW COMPLETELY DESTROYED BY LOGGING).</b> <b>A LOG ROAD HAS DESTROYED THE CORNER POINT AND BOTH ORIG. SNA9 BT'S.</b> <b>IN USING WHITMORE'S S.W. ALDER AS A WITNESS I DETERMINE THE TRUE CORNER POINT.</b>		
Signature <b>Leonard Whitmore</b> Title <b>Forestry Tech</b> Division <b>Timber</b> Headquarters <b>Hebo</b>	Date <b>2-15-68</b> 7100-52 REV. 65		

CORNER RECORD (PERPETUATION)	
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT <b>THE TRUE CORNER POINT IS LOCATED IN THE WEST WHEEL GAUDY ROAD.</b> <b>I SET A WITNESS CORNER 9 FT. WEST OF TRUE CORNER POINT</b> <b>A 3" X 3" POST 40" HIGH MARKED "1/4 WC"</b>	TRACK <del>is</del> of which is
ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE <b>I MARK 2 NEW WITNESSES FROM TRUE CORNER POINT:</b> <b>56" SAWED OFF SNA9, S. 70° E., 147 FT. TO FACE MKD. 1/4 S 30 CS BT.</b> <b>50" SAWED OFF SNA9, N. 44° E., 61 1/2 FT. TO FACE MKD. 1/4 S 19 CS BT.</b>	
<b>Leonard Whitmore, Tilla, Co. Deputy Surveyor</b> <b>1968</b> <b>John C. Smith 2/22/68</b>	
Work Done By _____ Title _____ Date _____ State Registration No. _____ or Agency _____	
Certified Cor. Record Prepared? Yes _____ No _____ Filed At _____ Date _____	
REMARKS <b>BRASSCAPPED BY BLM 1972</b>	