


File No. N-11 CORNER RECORD (LOCATION) Survey No. N-11
 T. 55 R. 9 D. HERB County TULLA State ORE. # 828

CORNER DIAGRAM DESCRIBE CORNER MONUMENT FOUND
 FOUND POSSIBLE REMNANT OF OLD POST LYING UPON THE GROUND.



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND 30" SNAG, S. 40° W., (NOT 45°) 17 LKS. WITH MARKS CUTTED OFF.
 FOUND 40" SNAG, N. 35° E., (NOT 40°) 39 LKS. WITH MARKS GONE STARTING ON A N-S SECTION LINE I RUN EAST WITH COMPASS AND CHAIN FOLLOWING AN OLD BLAZED LINE.
 AT 40 CHS. I FOUND THE ABOVE MENTIONED SNAGS.

PHOTO IDENTIFICATION
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Dept. By: _____
 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER. THEIR DISTANCES ARE ACCURATE BUT A VARIANCE OF BEARINGS IS EVIDENT AS IS VERY OFTEN FOUND IN CAUDLES BEARINGS.

PLANE COORDINATE POSITION
 State _____ Zone _____
 Estab. By _____ Agency _____ (over)

Signature	Title	Division	Headquarters	Date
Leonard Whitmore	Forestry Tech	Timber	Kelco	4-1-67

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 I SET 4" X 4" VINE MAPLE POST 3 FT. ABOVE GROUND.
 BRASSCAPPED BY BLM 1972

ACCESSORIES DESCRIBE NEW ST'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
 A 18" FIR, S. 65° W., 2 FT. I BLAZE X IN BARK.
 A 37" FIR, N. 6° W., 4 1/2 FT. I BLAZE X IN BARK.
 By Leonard Whitmore
 Witness: Robert Mearns
 THE CORNER IS ON A RIDGE RUNNING S. 60° W.

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS