

CORNER RECORD (PERPETUATION)

Loc. No. R-13 R.D. Hebo County _____ State _____
 55 R. 9 W. N.E. SLUSLAW State _____ #832
 Survey No. _____ No. 155

DESCRIBE CORNER MONUMENT FOUND
 I FOUND A 4"x4" WOOD POST 2 FT. ABOVE GROUND IN POOR
 CONDITION AND TIED TO A IRON AXLE LOCATED IN A
 STONE MOUND.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 W.W. HAYES, TILLA, CO. SURVEYOR IN 1887 RESTORED THIS
 CORNER BY SETTING A 4"x4" POST.
 M. WHITMORE IN 1954 SAW SCRIBE MARKS "YIMHILL" ON EAST
 SIDE OF POST. AT THAT TIME HE SAW MARKS "TILLAMOC
 CO. BT" ON A 48" SNAG, S. 27° W., 41 FT. SLOPE DISTANCE.

PHOTO IDENTIFICATION DATA DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 Photo No. E13-7-265 WHITMORE THEN MARKED 2 ADDITIONAL WITNESSES, OF
 Titled At _____ WHICH ARE NOW:
 Object Ident. _____
 Ident. By signature 36" FIR, N. 47° W., 49 FT. SLOPE DISTANCE. MKD. T5SR9WS 21 BT.
 36" FIR, N. 56° E., 12 1/2 FT. SLOPE DISTANCE. MKD. T5SR9WS 22 BT.

PLANE COORDINATE POSITION _____ Re-checked 2 FT.

State _____ Zone _____ CORNER IS ON NORTH EDGE OF AN OLD LEASING
 Signature _____ Title _____ Headquaters _____ Date _____
 5-8-67

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 SET 2"x30" IRON PIPE WITH FLARED BOTTOM AND BRASS CAP MARKED;
 JERVIN & LEONARD WHITMORE (FATHER & SON) ARE DEPUTY COUNTY
 SURVEYORS EMPOWERED TO RE-WITNESS AUTHENTIC ORIGINAL
 EVIDENCE
 12/19/60 J.L. Carlin County Surveyor

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
 I TIED TO THE EXISTING BT'S AND OLD SNAG AND SCRIBED ONE NEW BT PL
 NEW LOCATION TAGS AND PAINTING RED BANDS ON ALL OF THEM.

42" FIR, N. 47° W., 49 1/2 FT. WITNESS SCAR VISIBLE.
 40" FIR, N. 56° E., 11 1/4 FT. WITNESS SCAR VISIBLE.
 48" ROTTEN STUMP, S. 27° W., 38 3/4 FT.
 14" FIR, S. 83° W., 69 3/4 FT. MKD T5SR9WS 28 BT. NO TREES AVAILABLE TO S.E.

Work Done By WIGHTMAN Title CRLS Date 9-71 State Registration No. 942
 or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: TILLA, CO. COURTHOUSE Date 9-12-71

REMARKS
 I BUILT SMALL STONE MOUND AND RESET AXLE 1 FOOT EAST. I SET 6 1/2
 STEEL POST WITH "ATTENTION" AND "PROPERTY BOUNDARY" SIGNS 3 FEET
 WEST.

T5SR94
 S21/S22-
 S28/S27-
 61/56