

LAND CORNER RECORD
(Rectangular)

T.S. R.W. No. 1/4 Mer. W. 1/4 State OK N.F. S. 1036 RAW

Order Status 2-11

3. Original Description Vol. Page Where Located

4. Description of Corners:
 TILLA COUNTY SURVEY OF 1867 SET A POST AND MARKED 2 BT.
 28" SNAG, S. 60° W., 43 LKS.
 30" SNAG, N. 31° E., 163 LKS.

5. Investigation Notes:
 THE CORNER POINT SETS ON EDGE OF A LOGGING ROAD.
 POST IS MISSING.
 I FOUND A 40" SAWD OFF SNAG, N. 31° E., 163 LKS. WITH FAINT
 SCRIBE MARKS "1/4 SBT".
 FOUND 28" ROTTEN SNAG, S. 57° W. (NOT S. 60° W.), 43 LKS. WITH
 MARKS ROTTED OFF.

6. Signed _____ Title _____ Date 2-14-68

Photo Identification No. F1J-7-2CS

Plane Coordinate Position

Map Filed

Evaluation

Authentic

Needs Verif. Monument

Co-estab. Survey

Order Status

833

REWITNESS

I SET _____

"x" "x" " Post N.W. feet

" Hat Section S. E.

NEW ACCESSORY:

COMMENTS: LECWOOD, OKLAHOMA IS A TOWNSHIP
COUNTY SURVEYOR SAID TO BE
ATTENDING ORIGINAL SURVEY

IN THE PRESENCE OF: _____

DATE: _____

PHOTO # _____

TITLAWOOK COPYIA BEWITNE22 TITLE

* - County corner tag affixed.