

T-13
 T 5S R. 9W D. Hebo County Tillamook (&) Yamhill
 Merid. Tillamette F. Siuslaw State Oregon
 Survey No. **#839**

CORNER DIAGRAM DESCRIBE CORNER MONUMENT FOUND
 T5S R9W
 28 | 27 3/4
 Found a 4"x4"x30" old cedar post; a 3/4" iron pipe and
 fir post on dirt mound. Aluminium post with location
 poster & Bdg. sign 2' east.,

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 30" fir brs. N61E. 19.0 ft.
 face healed, did not open
 36" fir brs. N6 1/2 ft.

PHOTO IDENTIFICATION DATA scribing exposed
 Photo No. ETS-7-21
 Filed At: _____ (bearing tree tags attached)
 Object Ident. _____
 Ident. By L. Whitmore Signature _____
 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 Go east up old Nestuca Toll Road 1/4 mile from Hwy 22
 to Timber Edge, go south 3/2 chains to corner.

PLANE COORDINATE POSITION
 X _____
 Y _____
 Estab. By _____ Agency _____
 Signature T.O. McCullough Title _____ Division ORLS Headquarters 650 Date 1/70

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 Set a 2"x30" iron pipe with brass cap mkd
 T5S R9W
 1/4 28 | 27
 1969
 650

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
 Set steel fence post 3 feet north of brass cap with F.S. boundary sign
 attention sign facing west painted red band around bearing trees.
 Set old posts and 3/4" pipe behind cap.

Work Done By T.O. McCullough Title Surveyor Date 12/24/69 State Registration No. ORLS 650
 Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Witness to the above corner: R. Bryant
M. Wilson