

CORNER RECORD (SEARCH)

Index File No. _____ Tract or Survey No. _____ Cor. No. V-15
 T SS R. 9W R.D. Hebo County TILLA # 841
 Merid. Will. N.F. SIUSLAW State ORE.

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND GLO 1880 SET 12 X 10 X 6 STONE ON SUMMIT OF STEEP BLUFF. NO WITNESSES.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
FOUND 14 X 10 X 6 STONE. NO OTHER STONES ARE IN THE VICINITY.
THE POSITION OF THIS CORNER POINT CORRESPONDS WITH ORIGINAL PHYSICAL CALLS.
THE STONE IS LOCATED AT SUMMIT OF A STEEP BLUFF. 2 CHAINS EAST IS START OF DESCENT OVER STEEP BLUFF. 5 CHAINS NORTH IS BOTTOM OF STEEP BLUFF AS IN RECORDS.

PHOTO IDENTIFICATION DATA
 Photo No. E 15-9-187
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

OVER

Signature Leonard Whitmore Title Forestry tech Division Timber Headquarters Hebo Date 4-11-69 7100-52 REV. 65

CORNER RECORD (PERPETUATION)

MONUMENT; DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
SET 4 X 4 X 24 HARD LIMB POST MKD. "529" ON NE, S30 ON NW, S31 ON SW, S32 ON SE SIDES.
MARK A 14" FIR, N. 16° E, 7 FT. T5SR9WS29BT. SPRAY RED PAINT ON STONE, POST & WITNESS FACES.
A 12" FIR, S. 38° W, 6 FT. T5SR9WS31BT. PUT BEARING TREE SIGNS ON WITNESSES.
L. Whitmore, Forestry tech

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS
NOTE Leonard Whitmore is a DEPUTY COUNTY SHERIFF. To be witness of monument positive and accurate found.

Index File No. _____ T. _____ R. _____ M. _____ Tract or Surv. No. _____ Cor. _____