

CORNER RECORD (SEARCH) Tract or Survey No. **E-13**

Section **55** R. **10 W** R.D. **Hebo** County **Tilla** **#848**
 N.E. **SLUSMAN** State **ORE.**

FIG. DIAGRAM

DESCRIBE CORNER MONUMENT FOUND **1882** SET POST **4** LIND.
20" FIR, N. 62° E, 3.97 LIND.
40" FIR, S. 45° W, 2.40 LIND.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
FOUND A STEEL DRIVE SHAFT BAR IN GROUND ALONGSIDE
OLD ORIGINAL POST
FOUND 40" FIR SNAG, S. 45° W, 191.2 FT. WITH MARKS RATT
OFF.
THE NE BT IS MISSING.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Taken At _____
 Subject _____
 Taken By _____
 Signature _____

COORDINATE POSITION DATA
 Zone _____
 Taken By _____
 Agency _____

Signature: _____ Title: **Jewelry Store** Division: **J** Headquarters: **Hebo** Date: **2-13-76** 7100-52 (3/60)

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

WHITMORE, USFS, 1954 Re-witnessed 3 TRUCKS;
8" FIR, N. 62° E, 4 FT. WITH HEALED WITNESS FACE.
6" FIR, S. 30° 30' E, 3.4 FT. WITH HEALED WITNESS FACE.
6" SPRUCE, S. 14° W, 16 1/2 FT. WITH HEALED WITNESS FACE.

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor Record Prepared? Yes No Filed At _____ Date _____

REMARKS
ARANCE DUNN, LOCAL LANDOWNER, NOW 83 YEARS OLD AND LIVING ON THIS LAND
LIFE STATES THIS OLD ROTTED POST WAS THE ORIG. HE SAW SCRIBE MARK
DURING HIS BOYHOOD. IN FACT HIS FATHER WAS EMPLOYED BY THE GOV
VEYOR 1882 TO HELP MONUMENT THIS CORNER AS WELL AS OTHERS IN
HE TOWNSHIP.

Index File No. **T. 55 R. 10 W M. WILL** Tract or Surv. No. **Sec. Cor. 3-4-1-10**

L. Whitmore is a Deputy County Surveyor qualified to
re-witness bona fide old corners
attest to the County Co Surveyor