


CORNER RECORD (SEARCH)		Tract or Survey No.	
Index File No. <u>T 55 R 10W</u>	R.D. <u>HEBO</u>	County <u>TILLA</u>	Cor. No. <u>#852</u>
Merid. <u>Will.</u>	N.F. <u>SLUSLAW</u>	State <u>ORE</u>	
CORNER DIAGRAM 	DESCRIBE CORNER MONUMENT FOUND <u>TILLA COUNTY SURVEYOR 10 1896</u>		
	<p>Set post & MARKED;</p> <p>9" SPRUCE, S 87° 45' W, 98 LKS.</p> <p>9" SPRUCE, N. 3° 30' E, 72 LKS.</p>		
PHOTO IDENTIFICATION DATA	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND		
Photo No. _____	FOUND 4" X 4" X 24" DECAYED POST IN ROCK MOUND. ^{Post} IS MARKED "CS" ON EAST AND WEST SIDES.		
Filed At. _____	THE WITNESSES ARE GONE.		
Object Ident. _____	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER		
Ident. By _____	C.V.C.R.		
Signature _____			
PLANE COORDINATE POSITION DATA			
State _____ Zone _____			
X _____			
Y _____			
Signature <u>Leonard Whitmore</u>	Title <u>Township Clerk</u>	Location <u>Tilla</u>	Headquarters <u>Hebo</u>
			Date <u>2-7-70</u>
			7100-52

CORNER RECORD (PERPETUATION)			
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT			
<p>Set ALUMINUM post ALONGSIDE OLD CS CORNER AND ATTACHED A "DO NOT DESTROY" PENALTY SIGN. CORNER IS ON A NORTH SLOPE AND 30 FT. NORTH OF A RIDGE RUNNING EAST AND WEST.</p>			
ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE			
MARK 2 New BT'S:			
16" FIR, S. 32° 30' W, 25 ⁴ FT. TO NAIL HEAD AT SCRIBED "B", MARKED CW ^{1/6} S 4 E BTCS.			
18" FIR, S. 62° E, 37 ³ FT. TO NAIL HEAD AT SCRIBED "B", MARKED CW ^{1/6} S 4 E BTCS.			
PUT BEARING TREE SIGNS ON WITNESSES.			
<u>Leonard Whitmore, Tilla Co. deputy surveyor. 2-9-70</u>			
Work Done By _____	Title _____	Date _____	State Registration No. or Agency _____
Certified Cor. Record Prepared? Yes _____ No _____	Filed At _____	Date _____	
REMARKS			
Index File No. <u>T 55 R 10W</u>	Tract or Surv. No. <u>S 4</u>	Cor. No. <u>852</u>	