

Index 3 File No. <b>C-10</b>	CORNER RECORD (SEARCH)		Tract or Survey No.	Cor. No.
T 55 R 10W	R.D. Hebo	County Tillamook	# <b>853</b>	
Merid. Willamette	N.F. Siuslaw	State Oregon		
CORNER DIAGRAM		DESCRIBE CORNER MONUMENT FOUND		
		Found 4x4x24" decayed post in rock mount. Post is marked with C.S. on East and West side		
PHOTO IDENTIFICATION DATA		DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND		
Photo No. _____		16" fir brs. S22 1/2 W 24.6 ft - scribed CWL/16 S4 BT CS with tag		
Filed At. _____		18" fir brs. S62E 37.3 ft. - scribed CWL/16 S4 BT CS - with tag		
Object Ident. _____		DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER		
Ident. By _____ Signature _____		Go up Little Nestucca River for 1/4 mile - go left 1/4 mile to Rock pit then north for 500 ft - corner is 30 ft north of ridge running east and WEST		
PLANE COORDINATE POSITION DATA		Signature _____ Title _____ Div _____ Headquarters _____ Date _____		
State _____ Zone _____		ORLS 650		

CORNER RECORD (PERPETUATION)	
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT	
Set 2"x30" iron pipe with brass cap mkd	T55 R10W Sec 4 CWL/16 1970 650
ACCESSORIES - DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE	
Placed original post alongside pipe	
Set 2 fence posts with signs + 5 ft east facing north + 5 ft south facing west	
Work Done By <u>T.O. McCullough</u> Title <u>Surveyor</u>	Date <u>4/14/70</u> State Registration No. <u>ORLS 650</u> or Agency
Certified Cor. Record Prepared? Yes No	Filed At _____ Date _____
REMARKS	
witnesses to the above corner: Dick Rust Dave Dean	