

CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. Cop. No. C-10

File No. T. 5 S R. 10 W R.D. HEBO County TILLA. # 854
 Merid. WILL N.F. SIUSLAW State ORE.

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND TILLA. COUNTY SURVEYOR 1896
SET POST & MARKED;
9" SPRUCE, S. 87° 45' W., 98 LKS.
9" SPRUCE, N. 3° 30' E., 72 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
FOUND 4" X 4" X 24" DECAYED POST IN ROCK MOUND. POST
IS MARKED "CS" ON EAST AND WEST SIDES.
THE WITNESSES ARE GONE.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
OVER

PHOTO IDENTIFICATION DATA
 Photo No.
 Filed At
 Object Ident.
 Ident. By Signature

PLANE COORDINATE POSITION DATA
 State Zone
 X
 Y
 Estab. By Agency

Signature Leonard Whitmore Title Forestry Tech Division Timber Headquarters Hebo Date 2-9-70 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO SERVE EXISTING MONUMENT
SET ALUMINUM POST ALONGSIDE OLD CS CORNER AND ATTACHED A "DO NOT
DESTROY" PENALTY SIGN. CORNER IS ON A NORTH SLOPE AND 3 FT. NORTH OF
A BRIDGE RUNNING EAST AND WEST.

ACCESSORIES: DESCRIBE NEW BT'S, WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
MARK 2 NEW BT'S
16" FIR, S. 32° 30' W., 25 FT. TO NAIL HEAD AT SCRIBED "B", MARKED CW 1/6 S4 BTCS.
18" FIR, S. 62° E., 37 FT. TO NAIL HEAD AT SCRIBED "B", MARKED CW 1/6 S4 BTCS.
PUT BEARING TREE SIGNS ON WITNESSES.
Leonard Whitmore Tilla. Co. deputy surveyor. 2-9-70

Work Done By Title Date State Registration No. or Agency

Cancelled Cor. Record Prepared? Yes No Filed At Date

REMARKS

File No. T. 5 S R. 10 W N. WILL. Tract or Surv. No. Sec. 4 Cor. CW 1/6