

TILLAMOOK COUNTY REWITNESS #862

S.W.

COR. SEC 7 T 5S R 10 W., WM.

HISTORICAL: Book 5 PAGE 114

MAP B-391 W.E. ANDERSON

REPLACED FOUND PIPE WITH BRASS CAP.

FOUND: PLACED FOUND STONE ALONGSIDE BRASSCAP


CONDITION

FAIR	2" I.P. PLUGGED-TACK
GOOD	ORIGINAL CORNER STONE
GOOD	20" SPRUCE N75E 125 38
GOOD	N.W. CORNER OF CHURCH S19E 93 30

COMMENTS:

REWITNESS

1 SET 2" IRON PIPE WITH 3" BRASS CAP SET IN 10" TIE FILLED CONCRETE  
"x" "x" " Post N.W. feet



84" Hat Section 956E 0 86

NEW ACCESSORY:

CORNER TAG ON HAT SECTION  
YELLOW COR TAG ON RT.

COMMENTS: THIS CORNER IS LOCATED ± 100 FEET SOUTH OF  
US 101 AND ACROSS FROM THE OLD <sup>CANNERY</sup> ~~CHURCH~~ ~~SEEN~~ COUNTY  
ROAD AND ± 150 FEET EAST OF THE ORETOWN GOSPEL CHURCH.

IN THE PRESENCE OF: GALE ARTHUR-DAN McNUTT

DATE: 5-74

PHOTO#:

\* = County corner tag affixed.

TITLE