

USDA FOREST SERVICE
 Index File No. **J-13** CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. _____ Cor. No. _____
 T **5 S R 10 W** R.D. **Hebo** County **TILLAMOOK** #890
 Merid. **Will.** N.F. **SIUSLAW** State **ORE.**

CORNER DIAGRAM

SEC B-551

PHOTO IDENTIFICATION DATA
 Photo No. **ETJ-9-27**
 Filed At. _____
 Object Ident. **DIRECT**
 Ident. By **L. Whitmore**
Signature

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
Signature Agency _____

DESCRIBE CORNER MONUMENT FOUND (GLC 1882 USED 4" SPRUCE FOR CORNER & MARKED)
 20" ALDER, N. 50° W., 33 LKS.
 8" VINEMAPLE, N. 35° E., 34 LKS.
 7" VINEMAPLE, S. 20° E., 28 LKS.
 6" VINEMAPLE, S. 19° W., 39 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND 5/8" ROD 24" ABOVE GROUND. FOUND OLD 4x4x30 POST LYING ON GROUND ALONGSIDE ROD.
 FOUND SCRIBE MARKS ON POST CS - S16 - S10 - S15 RIQU. ON SIDES OF POST.
 FOUND 21" ALDER, N. 36° W., 2 FT. SCRIBE MARKS "SBT" SHOWING.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 FOUND 28" SPRUCE, N. 44° E., 2 FT. SCRIBE MARK "B" SHOWING.
 FOUND 23" SPRUCE, S. 12° E., 1 FT. SCRIBE MARKS "BT" SHOWING.
 CORNER IS LOCATED IN CLUMP OF 4 SPRUCE TREES ON A FENCE LINE. OLD VACANT HOUSE N. 55° E., 400 FT.

Signature: **Leonard Whitmore** Title: **Forestry Tech** Division: **Timber** Headquarters: **Hebo** Date: **3-12-71** 7100-52 (3/68)

TILLAMOOK COUNTY REWITNESS

DVIDE: _____ N. WHOIOL: SEC. _____
 COR. _____ T _____ R _____ W., WM. _____
 S. E. DLC. # _____

IN THE OFFICE OF HISTORICAL

CONDITION	FOUND:		

COMMENTS: