

CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. 6-21
 File No. 55 R. 10W R.D. Hebo County TILLA **#897**
 Merid. WILL N.F. SIUSLAW State ORE

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND GLD 1882 SET POST & MARKED:
10" ALDER, N. 30° E., 40 LKS.
8" ALDER, S. 5° W., 227 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
CARLICH REFERENCED BUT DID NOT MARK 2 FIRS
26" FIR, N. 20° W., 15 FT.
34" FIR, S. 5° W., 9 FT.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
FOUND REMNANT OF POST LYING ON GROUND WITH TIN
ATTACHED MARKED "JULY 6, 1955 1/4 COR. SET BY TRAN
SIT AND CHAIN TRAVERSE N-S J.L. CARLICH OLS #
287.

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature Leonard Whitmore Title Forestry Tech Division Timber Headquarters Hebo Date 4-1-69 7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
AT POINT THAT CARLICH'S POST SET, I SET 4x4 FIR LIMB POST AND
ATTACHED CARLICH'S MARKED CORNER TIN. I SCRIBE "1/4 S" ON WEST FACE OF
POST. SET ALUM. POST ALONGSIDE WITH "PENALTY TO DESTROY" SIGN ATTACHED

ACCESSORIES DESCRIBE NEW BT'S, WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
MARK 2 NEW WITNESSES:
1. FIR, S. 10° E., 8 FT. TO NAIL AT SCRIBED "B" MKD 1/4 S 12 BTCS.
2. FIR, N. 14° W., 15 FT. TO NAIL AT SCRIBED "B" MKD 1/4 S 11 BTCS.

Leonard Whitmore, Tilla Co. Deputy Surveyor 4-1-69

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____

Qualified Cor. Record Prepared? Yes _____ No _____ Filed At _____ Date _____

REMARKS

Tract or Surv. No. 11-12 Cor. 13