


Index File No. K-5	CORNER RECORD (SEARCH) (Ref. FSM 7151.4)		Tract or Survey No. _____	Cor. No. _____
5S R. 10W	R.D. HeBo	County TILLAMOOK		
Merid. Will.	N.F. SLUSLAW	State ORE.		
CORNER DIAGRAM 	DESCRIBE CORNER MONUMENT FOUND TILLAMOOK COUNTY SURVEYOR, 1888 SET 14x8x8 STONE AND MARKED; 8" ALDER, S. 88° W., 13 LKS. 5" ALDER, S. 84° E., 7 LKS. # 899			
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND FOUND 8x5x5 STONE FLUSH WITH GROUND, MARKS XVI ON WEST SIDE. AN OLD POST IS LYING UPON THE GR- OUND AT BASE OF ROCK. FOUND OLD DECAYED ALDER, S. 84° E., 7 LKS, LYING UPON THE GROUND. THE SW BT IS GONE.			
PHOTO IDENTIFICATION DATA Photo No. ETS-5-152 Filed At: _____ Object Ident. DIRECT Ident. By L. Whitmore <i>Signature</i>	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER			
PLANE COORDINATE POSITION DATA State _____ Zone _____ X _____ Y _____ Estab. By _____ <i>Agency</i>	Signature Leonard Whitmore Title Forestry Tech Divis Timber Headquarters Hebo Date 3-1-71 7100-52 (3/69)			

CORNER RECORD (PERPETUATION)	
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT SET OLD POST ON EAST SIDE OF ORIGINAL STONE,	
ACCESSORIES: DESCRIBE NEW BT'S, WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE I SCRIBE 2 TREES; 66" SAWED OFF DOUBLE SPRUCE, N. 25° E., 13 1/2 FT. TO NAIL HEAD AT SCRIBED "A" SCRIBED N 1/4 S 17 CSBT. 74" SPRUCE, S. 4° W., 18 FT. TO NAIL HEAD AT SCRIBED "B". SCRIBED N 1/4 S 18 CSBT	
Work Done By Leonard Whitmore	Title Tilla. County Deputy Surveyor
Certified Cor. Record Prepared? Yes <input type="checkbox"/> No <input type="checkbox"/>	Filed At: _____ Date _____
REMARKS PAINTED FACES OF BT'S RED AND ATTACH LOCATION SIGNS ON BT'S.	
Index File No. T. 5 S. R. 10 W. M.	Tract or Surv. No. West - N 1/4, Cor. SEC. 17