


U.S. FOREST SERVICE 670 940-117

Index File No. **J-5-6** CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. _____ Con No. _____

55 R. **10W** R.D. **HeBo** County **TILLA.** **#901**

Merid. **WILL.** N.F. **SIVSLAW** State **ORE.**

CORNER DIAGRAM


DESCRIBE CORNER MONUMENT FOUND **GL 1872 SET 14x8x6 STONE.**

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
FOUND 12x10x7 STONE WITH MARKS XXXII ON NORTH SIDE. THIS CORNER IS A 1/2 CORNER TO LOTS IN SECTION TO THE NORTH.
I SET 1/2 GALV. PIPE ALONGSIDE STONE.

PHOTO IDENTIFICATION DATA
 Photo No. **ETT-5-152**
 Filed At: _____
 Object Ident. **WITHIN 50 FT.**
 Ident. By **L. Whitmore**
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
I ATTACH A LOCATION TIN ON #46" SPRUCE STUMP 15 FT. HIGH, N. 77° E., 11 FT.
L. Whitmore, Forestry Tech

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____ Agency _____

Signature **L. Whitmore** Title **Forestry Tech** Division **Timber** Headquarters **HeBo** Date **3-5-71** 7100-52 (3/68)

REWITNESS

I SET

Post **N.W.** **feet**
 Hat Section **S. E.**

NEW ACCESSORY:

COMMENTS:

IN THE PRESENCE OF:

DATE: _____

PHOTO: _____

TITLE

County corner tag affixed.

REMARKS:

L. WHITMORE IS A DEPUTY CS. QUALIFIED TO RE-WITNESS POSITIVE OLD EVIDENCE OF ORIGINAL MONUMENTS