


Index File No. <u>65</u>	CORNER RECORD (SEARCH) (Ref. FSM 7151.4)		Tract or Survey No. _____	Cor. No. _____
T. <u>5S</u> R. <u>10W</u>	R.D. <u>HEBO</u>	County <u>TILLA</u>	# <u>903</u>	
Merid. <u>WILL.</u>	N.F. <u>SIUSLAW</u>	State <u>ORE.</u>		
CORNER DIAGRAM 	DESCRIBE CORNER MONUMENT FOUND <u>GLO 1872 SET POST & MARKED</u> <u>16" SPRUCE, N. 10° W., 42 LKS.</u> <u>6" ALDER, S. 30° E., 25 LKS.</u>			
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND <u>FOUND 48X5X5 POST IN POOR CONDITION SCRIBED</u> <u>"1/4 S ON S., # 287 ON N. SIDES."</u> <u>A TIN IS ATTACHED TO TOP OF POST MARKED "1/4</u> <u>CORNER 18/17 SET BY PROPORTIONMENT N-S TRANSIT &</u> <u>CHAIN J. L. CARLICH # 287 BELL 4-57.</u>			
PHOTO IDENTIFICATION DATA Photo No. <u>ETJ-5-152</u> Filed At. _____ Object Ident. <u>DIRECT</u> Ident. By <u>L. Whitmore</u> <i>Signature</i>	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER <u>OLD LOGGING IS ON WEST SIDE AND MUCH BLOWDOWN</u> <u>ON EAST SIDE.</u> <u>I CANNOT FIND ANY IDENTIFIABLE REFERENCES.</u> <u>ON A STEEP NORTH SLOPE.</u>			
PLANE COORDINATE POSITION DATA State _____ Zone _____ X _____ Y _____ Estob. By _____ <i>Agency</i>	Signature <u>Leonard Whitmore</u> Title <u>Forestry Tech</u> Division <u>Timber</u> Headquarters <u>Hebo</u> Date <u>3-12-71</u> 7100-52 (3/68)			

REWITNESS

No additional information

DATE: _____

2° E° DEC° _____
COK° _____
1° PHOTO# 2EC° _____
TILLAMOOK COUNTY BEWITNESS TITLE _____

* = County corner tag affixed.