

Index File No. R-6 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. _____ Cor. No. _____

T 55 R. 10W R.D. HEBO County TILLA # 907

Merid. Will. N.F. SLUSLAW State _____

CORNER DIAGRAM

 N
 20
 W $\frac{1}{16}$
 X
 29

DESCRIBE CORNER MONUMENT FOUND W.M. MARKHAM, ORLS #1842, 12-1952 SET $1\frac{1}{2}$ " IRON PIPE AND SCRIBED 2 WITNESSES; 4 FT. SPRUCE STUMP, N. 70° W., 120 FT. 4 FT. SPRUCE STUMP, S. 74° E., 18 FT.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 I FOUND $1\frac{1}{2}$ " PIPE RUSTED AND IN POOR CONDITION. FOUND 4 FT. SPRUCE STUMP, S. 74° E., 18 FT. WITH SCRIBE MARKS ROTTED OFF. FOUND 4 FT. SPRUCE STUMP, N. 70° W., 120 FT. WITH FAINT SCRIBE MARKS. A TIN IS ATTACHED WITH

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 MARKS " $\frac{1}{16}$ " COR. BEARS S. 70° E., 120 FT."
 W.M.
 M.W.
 ROY DUNN 12-22-52

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____ Agency _____

PHOTO IDENTIFICATION DATA
 Photo No. ETJ-5-154
 Filed At. _____
 Object Ident. WITHIN 50 FT.
 Ident. By J. Whitmore Signature

I PAINT RED ON WITNESS FACES AND ATTACH LOCATION TAGS. HANG RED FLAGGING AROUND CORNER.

Signature Leonard Whitmore Title Forestry Tech Division Timber Headquarters Hebo Date 3-18-71 7100-52 (3/68)

REWITNESS

I SET _____ feet

_____ N.W. _____
 _____ S.E. _____

NEW ACCESSORY:

COMMENTS:

IN THE PRESENCE OF: _____

DATE: _____

PHOTO: 2EC

LITTYWOCK CORNER TAG AFFIXED