

No. 7 Mer. W. L. State OR N. F. STUDLEY Dist. W. 5  
 Corner Status TSSRIOW R-11 3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_  
 4. Description of Corners:  
 TILLA COUNTY SURVEYOR 1887 SET A POST AND MARKED 2 BT  
 28" SNAG, S. 60° W., 43 LKS.  
 30" SNAG, N. 31° E., 163 LKS. #909

5. Investigation Notes:  
 THE CORNER POINT SETS ON EDGE OF A LOGGING SKID ROAD.  
 POST IS MISSING.  
 I FOUND A 40" SAWED OFF SNAG, N. 31° E., 163 LKS. WITH FAIR  
 SCRIBE MARKS "1/4 SBT"  
 FOUND 28" ROTTED SNAG, S. 57° W. (NOT S. 60° W) 43 LKS. WITH  
 MARKS ROTTED OFF.

Photo Identification  
 Photo No. ELU-7-265  
 Taken By: \_\_\_\_\_  
 Plane Coordinate Position  
 Zone \_\_\_\_\_  
 Date \_\_\_\_\_  
 Evaluated \_\_\_\_\_  
 Authentic   
 Needs Verif. \_\_\_\_\_ Monument \_\_\_\_\_  
 Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_  
 End Status \_\_\_\_\_

6. Signed Leonard Whitmore Title Forestry Tech Date 2-14-68

**PERPETUATION RECORD**

Monument: I SET 1" yellow pipe 3" ABOVE GROUND AND MARK 2 New B

Accessories  
 16" FIR, S. 79° E., 15<sup>3</sup> FT. MKD. 1/4 S 28 CS BT.  
 16" FIR, N. 50° W., 11 FT. MKD. 1/4 S 21 CS BT.  
 PUT CS LOCATION TAGS ON BT.  
 Witness: Fred Johnson

Leonard Whitmore, Tilla. Co. Deputy Surveyor 1968

Set By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_  
 Agency \_\_\_\_\_  
 13. Recorded By \_\_\_\_\_ Volume \_\_\_\_\_ Page \_\_\_\_\_  
 (Date) (City) (County) (S)

Remarks: LEONARD WHITMORE IS A PERPETUATION SURVEYOR  
 EMPLOYED TO RE-WITNESS ORIGINAL ORIGINAL  
 EVIDENCE