

HISTORICAL MAPS	MAPS	Book	Page
A-82	A-2286	"P-1"	134
A-168	B-76	Hays "F"	54
A-219	B-427 = B-470	1	89
A-1113	B-807	4	74
A-1186	F-27-27	6	46
	A-2286		

CONDITION Fair FOUND: 1/2" Iron Pipe ± 12" Deep (Plug & Tack)

We temporarily witnessed the found monument and placed a 2" Iron Pipe over the found Pipe. This raised the position to ± 6" above ground surface. We checked our witnesses for positioning of the monument and placed a nail in the 2" Iron Pipe at the proper position. (Pipe is on an angle)


COMMENTS:

REWITNESS

2" IRON PIPE WITH PLUG & TACK

I SET 1 1/2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE & CEMENT @ POSITION OF

"x"	"x"	" Post	N.W.	feet
x	86"	Hat Section	S.	15 FEET



NEW ACCESSORY:		
1/2" ALDER	N 46° W 55' 45"	C 1/4 S 25 BTCS

COMMENTS: THIS CORNER IS LOCATED ON THE WEST SIDE OF A SMALL CREEK ± 20' SOUTH OF OF A FENCE CORNER THE FENCE RUNS WEST & NORTH FROM THE FENCE CORNER. GALE ARTHUR DAN MCNUIT 9-80

IN THE PRESENCE OF: Gale Arthur
Roger Knipple

DATE: June 1972 PHOTO#: SEC: TILLAMOOK COUNTY REWITNESS TITLE

* = County corner tag affixed.