

TILLAMOOK COUNTY REWITNESS # 946

W. 36 SEC.
COR. 35+36 T. 5 S R 11 W., WM.
E. 35

HISTORICAL: GLO Pg 18 5511

Book	PAGE	MAPS
2	565	A-1340
		A-1341
		C-331


CONDITION DISTURBED FOUND: 1" HEXAGON BAR

NOT FOUND	12" SPRUCE	S 74° W 12 LKS	GLO Pg 18
NOT FOUND	8" SPRUCE	S 40° E 12 LKS	GLO Pg 18
NOT FOUND	6" ALDER	S. 60° W. 63'	BK 2 Pg 565
FOUND PROBABLY DISTURBED Now N 65° E 113' TO FACE	6" ALDER	N. 85° E. 11'	BK 2 Pg 565

COMMENTS:

REWITNESS

I SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE
& CEMENT FROM A TIE TO NESKOWIN HEIGHTS
84" Hat Section EAST 15 FEET



NEW ACCESSORY:

POWER POLE.	S. 44° W. 77'	△

COMMENTS: THIS CORNER IS LOCATED ± 20' EAST
OF A ROAD IN NESKOWIN HEIGHTS SUBDIVISION. THE CORNER
POINT WAS DESTROYED BY CAT WORK. REMAINING ALDER BT APPEARS
TO HAVE BEEN DISTURBED. SEE ATTACHED FIELD NOTES

LAYED FO. IRON BAR IN THE PRESENCE OF: GALE ARTHUR DAN MCNUIT
ALONGSIDE MONUMENT

DATE: 4-30-79

PHOTO#: REC 2
LITWOOD COUNTY REWITNESS

TITLE

* = County corner tag affixed.