

CORNER RECORD (SEARCH) (Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

Index File No. 1-1

T. 6 S. R. 8 W. R.D. Heise County TILLAMOOK

Merid. Will. N.F. SINSLAW State ORE. # 948

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND
 GLO 1687 SET POST & MARKED;
 15" FIR, N. 77° 45' E, 190 LKS.
 22" FIR, S. 16° 30' E, 103 LKS.
 12" FIR, N. 45° W, 100 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND 1" GALV. PIPE WITH 4" X 4" WHITE POST
 FOUND 36" SAWED-OFF FIR STUMP, N. 77° 45' E, 125 FT.
 WITH SCRIBE MARKS "T6 SREWS 6 BT" SIFLOWING
 THE SE BT IS A SAWED-OFF STUMP,
 THE NW BT IS MISSING.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 FOUND 2 SCRIBED TREES BY OSBF;
 16" FIR, N. 21° E, 23 FT. DISTANCES ARE TO SIDE CENTER
 22" FIR, S. 20° E, 14 FT.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____

Signature Edward W. Whitmore Title Forestry Tech. Inspector Div. Heise Headquarters _____ Date 3-4-74 7100-52 (1)

CORNER RECORD (SEARCH)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES. DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Verified Cor. Record Prepared? Yes No Filed At _____ Date _____

REMARKS