


Index File No. E-11	CORNER RECORD (SEARCH) (Ref. FSM 7151.4)		Tract or Survey No. #954	Cor. No.
T 6S R. 9W	R.D. HeBO	County TILLAMOOK		
Merid. Will	N.F. SILVSLAW	State ORE.		
CORNER DIAGRAM 	DESCRIBE CORNER MONUMENT FOUND G.LO 1908 SET HEM. POST 4 MKD) 16" Hem, N.18°E, 8 LKS. 10" Hem, S.86°E, 8 LKS.			
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND POST GONE, FOUND 12" Hem, S.86°E, 5 1/2 FT. WITH OPEN FACE BUT ALL SCRIBING IS ROTTED AWAY. FOUND 22" Hem, N.18°E, 5 1/2 FT. WITH HEALED WITNESS FACE.			
PHOTO IDENTIFICATION DATA Photo No. _____ Filed At. _____ Object Ident. _____ Ident. By _____ <i>Signature</i>	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER IS ON E. SLOPE 70 FT. E. OF A RIDGE TO TOP			
PLANE COORDINATE POSITION DATA State _____ Zone _____ X _____ Y _____				
<i>Signature</i> Leonard Whitmore	Title Forestry Tech	Division Tillamook	Headquarters Medford	Date 3-18-74

CORNER RECORD (PERPETUATION)			
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT			
SET 3/8" IRON ROD. SET ALUMINUM POST 1 FT. S. OF CORNER POINT. ATTACH "PENAL DESTROY" SIGN.			
ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE			
SCRIBE ONE NEW BT, 30" FIR, S.69°W, 13 FT. SCRIBED "1/4 S 9 BT." DISTANCE IS TO SIDECENTER FROM THE CORNER POINT IS A 12" Hem, N.27°E, 7 1/2 FT. WITH OLD MARKS "BM 1066."			
Work Done By _____	Title _____	Date _____	State Registration No. or Agency _____
Certified Cor Record Prepared? Yes _____ No _____	Filed At _____	Date _____	
REMARKS			
INDEX FILE NO. T. 6S R. 9W M. TRACT OR SURV. NO. 1/4 COR. 4/9			