

Index File No. E-11

CORNER RECORD (SEARCHED) (Ref. FSM 7151.4)

Survey No. \_\_\_\_\_ No. \_\_\_\_\_

T. 6 S R. 9 W


R.D. HeBo County TILLAMOOK

#956

Merid. Will

N.F. SLUSLAW State ORE.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND G.L.O 1908 SET HEM. POST 4 MK  
16" Hem, N.18°E, 8 LKS.  
10" Hem, S.86°E, 8 LKS

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND  
POST GONE.  
FOUND 12" Hem, S.86°E, 5 1/2 FT. WITH OPEN FACE 13 FT  
ALL SCRIBING IS ROTTED AWAY.  
FOUND 22" Hem, N.18°E, 5 1/2 FT. WITH HEALED WITNESS  
FACE.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
 Signature \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER  
CORNER IS ON E. SLOPE 70 FT. E. OF A RIDGE TOP.

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Estab. By \_\_\_\_\_  
 Agency \_\_\_\_\_

Signature Leonard Whitmore Title Forestry Tech Division Timber Headquarters Nelco Date 3-18-74 7100 52 1 68

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT  
SET 1/8 IRON ROD.  
SET ALUMINUM POST 1 FT. S. OF CORNER POINT. ATTACH PENALTY TO  
"BUSTROY" SIGN.

ACCESSORIES. DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE  
SCRIBE ONE NEW BT, VAR. 21°  
30" FIR, S.69°W, 13 FT. SCRIBED "1/4 S 9 BT." DISTANCE IS TO SIDECENTER  
FROM THE CORNER POINT IS A 12" Hem, N.27°E, 7 1/4 FT. WITH OLD SCRIBED  
MARKS "BM 1066."

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_ or Agency \_\_\_\_\_  
 Certified Cor. Record Prepared? Yes No Filed At \_\_\_\_\_ Date \_\_\_\_\_

REMARKS  
Leonard Whitmore is a deputy  
County Surveyor & empowered to  
re-visit new positive old corner  
evidence  
7/23/74 J.L. Carter  
County Surveyor

Index File No. T. 6 S R. 9 W M. Tract or Surv. No. 1/4 Cor. 4/4