

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Index File No. C-9 Tract or Survey No. _____
 T. 6S R. 9W R.D. HeBO County TILLA
 Merid. WILL N.F. SUSLAW State ORE. **#758**

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT ~~FOUND~~ CL 1908 SET PAST & MARKED
10" FIR, S. 80° 30' E., 4 LKS.
10" FIR, S. 50° 30' W., 18 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
FOUND DEAD FIR STUB, S. 80° 30' E., 2 1/2 FT. WITH
VISIBLE SCRIBE MARKS "1/4 SBT."
THE S.W. BT IS A BADLY DECAYED STUMP,

PHOTO IDENTIFICATION DATA
 Photo No. ETJ-6-14
 Filed At. _____
 Object Ident. WITHIN 30'
 Ident. By L. WHITMORE
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
I SCRIBE ONE NEW WITNESS;
26" HEM., S. 58° W., 14 1/2 FT. TO SIDE-CENTER,
SCRIBED "1/4 SSBT."
PUT "PENALTY TO DESTROY SIGN ON S.W. BT.
COR. IS ON N. SLOPE ABOUT 100 FT. N. OF A LEG ROAD

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
Agency

Signature L. Whitmore Title Forestry Tech. Timber Division Nob. Headquarters Nob. Date 3-20-74 7100-12 (3-65)

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
SET 3/8 IRON ROD.

L. Whitmore, Tillamook County Deputy Surveyor 1974

ACCESSORIES. DESCRIBE NEW BT'S, WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
L. Whitmore is a Deputy County Surveyor
empowered to re-witness positive
old corner evidence 7/23/74 J. L. Carter
County Surveyor

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS