


Index File No. C-9	CORNER RECORD (SEARCH) <small>(Ref. FSM 7151.4)</small>	Tract or Survey No. _____	Cor. No. _____
T. 6S R. 9W	R.D. Hebo County TILLAM.	#959	
Merid. Will.	N.F. SINSLAW State ORE.		
CORNER DIAGRAM 	DESCRIBE CORNER MONUMENT FOUND GLO. 1908 SET POST. & MARKED 10" FIR, S. 80° 30' E., 4 LKS. 10" FIR, S. 50° 30' W., 18 LKS.		
PHOTO IDENTIFICATION DATA Photo No. ETT-6-14 Filed At. _____ Object Ident. WITHIN 30' Ident. By L. W. H. T. M. O. R. E.	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND FOUND DEAD FIR STUB, S. 80° 30' E., 2 1/2 FT. WITH VISIBLE SCRIBE MARKS "1/4 SBT." THE S.W. BT IS A BADLY DECAYED STUMP.		
Signature Leonard W. Whitmore Title Division Forestry Tech. Timber No. 3-20-74	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER I SCRIBE ONE NEW WITNESS; 26" Hem., S. 58° W., 14 1/2 FT. TO SIDE-CENTER, SCRIBED "1/4 SSBT." PUT "PENALTY TO DESTROY SIGN ON S.W. BT. COR. IS ON N. SLICE ABOUT 100 FT. N. OF A LOG ROAD.		

CORNER RECORD (PERPETUATION)
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT SET 3/8 IRON ROD.
ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
Leonard W. Whitmore, Tillamook County Deputy Surveyor 1974
Work Done By _____ Title _____ Date _____ State Registration No. _____ or Agency _____
Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____
REMARKS