

CORNER RECORD (SEARCH)

Index File No. _____ Tract or Survey No. _____ Cor. No. 7-5
 T. 6S R. 9W R.D. HEBO County TILLAMOOK **#961**
 Merid. Will. N.F. SIUSLAW State ORE.

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND
 FOUND 4"x4" POST LYING UPON THE GROUND IN POOR CONDITION WITH VISIBLE MARKS "58" (ORIGINAL)

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND 11" HEMLOCK, N.44°40'W., 30LKS. WITH VISIBLE MKS T6SR9WS6B.
 FOUND 20" HEMLOCK, STUB, 10FT. HIGH, S.46°30'E., (NOT S.33°E AS IN ORIG. NOTES) 30LKS. WITH VISIBLE MKS. T6SR9WS8BT.
 ON THE NORTH SIDE OF THE ABOVE BT IS VISIBLE MKS. BMS

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 THE REST IS ROTTED AWAY.
 THE S.W. BT IS A ROTTED STUB.
 THE N.E. BT IS GONE.

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature Edward Whitmore Title Forestry Tech TM Headquarters Hebo Date 7-22-65 7100-52 REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 SET 4"x4" HARD POST MKD. 55 ON N.E., 56 ON N.W., 57 ON S.W., AND 58 ON S.E. SIDES.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
 MARK 4 NEW BT'S:
 51 SNAG, N.11°W., 27 1/2 FT. MKD. T6SR9WS6BT
 52 SNAG, S.80°W., 5 FT. MKD. T6SR9WS7BT
 53 SNAG, N.83°30'E., 30 FT. MKD. T6SR9WS5BT
 58 Hem., S.53°E., 27 FT. MKD. T6SR9WS8BT

By L. WHITMORE
 WITNESSES:
ED GORY
L. CUMMINS
G. BERGSTROM

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At. _____ Date _____

REMARKS
 EDWARD WHITMORE IS A DEPUTY COUNTY SURVEYOR EMPOWERED TO RE-WITNESS POSITIVE EVIDENCE OF OLD CORNERS
J. L. Carlin 8/75

Index File No. _____ T. _____ R. _____ M. _____ Tract or Surv. No. _____ Cor. No. _____