


Index: **C-5** CORNER RECORD (SEARCH) Tract or Survey No. **7100-52 (3/68)**  
 File No. **65 R. 9W** (Ref. FSM 7151.4) County **TILLAMOOK** No. **#963**  
 Merid. **Willi** R.D. **Hebe** N.F. **SLUSLAW** State **ORE.**



DESCRIBE CORNER MONUMENT FOUND **GLO 1908 SET POST & MKD;**  
**16" SPRUCE, N. 62°15'E, 14 LKS.**  
**12" FIR, S. 21°W, 18 LKS.**

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND  
**FOUND 1/2" PIPE ALONGSIDE OLD ORIGINAL POST 4"x6"x**  
**24" ROTTED AND POOR CONDITION.**  
**LOGGING HAS APPARENTLY DESTROYED THE ORIGINAL BT'S.**  
**M. WHITMORE, 1950 FOUND SCRIBE MARKS ON ORIGINAL POST,**

PHOTO IDENTIFICATION DATA  
 Photo No. \_\_\_\_\_  
 Filed At. \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
 Signature \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER  
**CORNER IS UNDER EAST EDGE OF A LOG. A CR,**  
**IS ABOUT 100 FT. NORTH. LOG ROAD IS 200 FT. WEST**

PLANE COORDINATE POSITION DATA  
 State \_\_\_\_\_ Zone \_\_\_\_\_  
 X \_\_\_\_\_  
 Y \_\_\_\_\_  
 Estab. By \_\_\_\_\_  
 Agency \_\_\_\_\_

Signature **L. Whitmore** Title **Forestry Tech** Div. **Timber** Headquarters **Hebe** Date **8-22-73**

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT  
**SET 1/2" PIPE**

ACCESSORIES: DESCRIBE NEW BT'S, WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE  
**SCRIBE 2 NEW BT'S;**  
**13' DOUBLE HEM, N. 22°E, 12 1/2 FT. SCRIBED "1/4 S 5 BT" SIDE-CENTER,** DISTANCES ARE TO  
**9" HEM, N. 35°W, 17 FT. SCRIBED "1/4 S 6 BT"** VAR. 21"  
**7/23/74 L. Whitmore**  
**County Surveyor**

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_  
 or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes No Filed At: \_\_\_\_\_ Date \_\_\_\_\_  
 REMARKS  
**L. Whitmore is a Deputy County Surveyor**  
**empowered to re-witness positive**  
**evidence of all corners**