


T6SR. LOW WILL. R.D. HEBO County TILLA USFS FILE # A-9
 N.F. SIUSLAW State ORE.

GRAM CLOSING CORNER


DESCRIBE CORNER MONUMENT FOUND GLO 1890 MKD; 8" HEM. FOR CORNER, AND 3 BT'S;
10" SPRUCE, S. 50° E., 21 LKS.
12" ALDER, S. 10° W., 25 LKS.
4" ALDER, N. 7° W., 47 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 BY RECORD M. WHITMORE, USFS, 1950 FOUND 2. BT'S FALLEN WITH VISIBLE SCRIBING. He set 1 1/2" IRON PIPE.
4-16-73 I FOUND THE 1 1/2" PIPE.
FOUND REMNANT OF A ROTTED ALDER S. 10° W. TO STUMP HOLE.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
THE S.E. AND N.W. BT'S ARE GONE.
FOUND 40" FIR, S. 70° W., 4. FT. TO FACE WITH AN OLD RUSTED LOCATION SIGN. IN ADDITION IS A MORE RECENT LONGVIEW-FIBRE LOCATION SIGN.
I BLAZE X ON FACE.

SIGNATURE: Whitmore Title: Forestry tech Division: Timber Headquarters: Hebo Date: 4-16-73 710 (3/68)

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVID
Leoland Whitmore is a Deputy County Surveyor empowered to be witness positive identifiable found monuments in connection with his USFS work.
J.L. Conlin CS
12/72

Work Done By: _____ Title: _____ Date: _____ State Registration No. or Agency: _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date: _____

REMARKS
FOUND 16" HEM, N. 39° E., 3 FT. WITH OLD CRUISER MARK A. BLAZE X ON FACE AND ATTACH LOCATION SIGN.
OLD ORIGINAL BLAZES ARE TO THE SOUTH, EAST, AND WEST.
CORNER IS LOCATED ON A EAST SLOPE.
Leoland Whitmore, USFS, 4-16-73