


Index File No. J-9 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. #988 Cor. No. 8
 T. 6S R. 10W R.D. HEBO County TILLAMOOK
 Merid. WILL. N.F. SIUSLAW State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND GLO 1840 SET POST & MARKED

10" HEM., S. 78 1/2° E., 40 LKS.
 20" SPRUCE, N. 74° E., 67 LKS.
 20" SPRUCE, N. 62° W., 64 LKS.
 12" HEM., S. 39° W., 40 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FOUND 60" SPRUCE, N. 62° W., 42 1/2 FT. WITH HEALED W
 NESS FACE.
 FOUND 14" HEM., S. 78 1/2° E., 26 1/2 FT. WITH PARTIALLY
 CHOPPED OPEN AND ROTTED FACE.
 FOUND 23" DEAD SPRUCE N. 74° E., 44 FT. WITH VISIB
 SCRIBE MARKS "S 9 BT."

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH COR

THE S.W. BT IS MISSING.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____
 Estab. By _____
 Agency _____

Signature Leonard Whitmore Title Forestry Tech Div. Tillamook Headquarters Nebo Date 2-23-72 7100-52 (3/6)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

SET 5/8 IRON ROD AT CORNER POINT.
 SET IRON FENCE POST 1 FT. SOUTH OF THE CORNER WITH A "PENALTY
 DESTROY" SIGN ATTACHED.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

PUT LOCATION SIGNS ON FRONT AND BACK OF BT'S PAINT RED
 BAND AROUND TREES.

Signature Leonard Whitmore Title Tilla. Co. dep. surveyor Date 2-23-72

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At _____ Date _____

REMARKS
Whitmore is a Deputy County Surveyor qualified to Re-witness
positive evidence of original GLO monuments
of Carter & Co. Surveyor

Index File No. _____ T. 6S R. 10W M. Hebo Tract or Surv. No. 988 Cor. 8