

CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 I SET A 1" GALV. PIPE 40" ABOVE GROUND 50 YDS WEST OF A SMALL B...
 (ORIG. NOTES) AND ABOUT 10 YDS EAST OF THE WEST ALDER STUMP. 992

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
 I MARK 4 NEW BT'S:
 FIR, S. 77° 30' E, 26 FT. HORIZONTAL DIST. MKD. T6SR10WS 14 BT.
 SPRUCE, N. 66° E, 49 FT. SLOPE DIST. MKD. T6SR10WS 11 BT.
 HEM., N. 7° W, 51 1/2 FT. SLOPE DIST. MKD. T6SR10WS 10 BT.
 HEM., S. 34° W, 54 FT. HORIZ. DIST. MKD. X BT.

Leonard Whitmore, Tilla. Co. Dep. Surveyor Witness: GLEN HORNER

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS
 NOTE Leonard Whitmore is a Deputy County Surveyor qualified to
 REMONUMENT & RE-WITNESS POSITIVE OLD CORNERS FOUND
 J. L. Condit
 County Surveyor
 10/10/67

TILLAMOOK COUNTY REWITNESS

CORNER RECORD (SEARCH) Tract or Survey No. _____ Cor. No. J-17

65 R. 10 W. D. HEBO County TILLA
 id. WILK N.F. SIUSLAW State ORE

NER DIAGRAM
 10011
 15014
 CS File Book Page 3

DESCRIBE CORNER MONUMENT FOUND
 FOUND 1" GALV. PIPE 40" ABOVE GROUND SET BY
 L. WHITMORE. 6-1-67.
 Refer to Book 3 Page 276 County Records
 GLO T6SR10W Pgs 7 & 8 AND 73 & 74 County Records

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND ORIG. ALDER, WEST, 10 YDS. AND AN ALDER, N. 84° W,
 10 YDS. FALLEN UPON THE GROUND AND BADLY DETERIORATED. BOTH
 HAD GROWN FROM THE SAME STUMP. FOUND VISIBLE BUT IL-
 LEGIBLE SCRIBE MARK ON A PIECE OF ALDER BARK UPON THE GROUND
 WRITTEN TESTIMONY IN R.S. FILES BY H. LILLIGREN, FORESTER, 1-2

STATES THAT AT THAT TIME HE SAW ALL SCRIBE MARKS ON 3
 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 THE THEN STANDING WEST AND NW ALDERS. HE ALSO STATES A
 LARGE BOULDER IN THE CREEK FORMING A 6 FT. WATERFALL
 LIES ABOUT 30 YDS. TO THE N.E.
 I FOUND THE ABOVE AS STATED

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 PLANE COORDINATE POSITION
 State _____ Zone _____

1011
1514

TILLAMOOK COUNTY REWITNESS

N.W. 14th SEC. 1011
COR. 1514 T 6S R 10 W., WM.
S. E. 10

HISTORICAL: G.L.O. T6S R10W Pg. 73 SET POST ±1896

BOOK	PAGE	FRONT & BACK	OF PAGE
3	276		


CONDITION	FOUND:		
GONE	16" ALDER	WEST 10 LKS	GLO Pg 73
GONE	20" ALDER	N 84° W. 10 LKS	GLO Pg 73
GONE	10" ALDER	N 27° E. 33 LKS	GLO Pg 73
FD. NOW 40" S. 77° 30' E. 26° FT	28" FIR	S. 77° 30' W. 26°	BK. 3 Pg 276
FD. BURNT STUMP SCRIBING VISIBLE	66" SPRUCE	N 66° E. 49' SLOPE DIST.	BK. 3 Pg 276
FD. BURNT STUMP ± 10' TALL FACE ON OUT	30" HEMLOCK	N. 7° W. 5 1/2 SLOPE DIST.	BK. 3 Pg 276
FD. GOOD NOW 14"	8" HEMLOCK	S. 34° W. 548	BK. 3 Pg 276

COMMENTS:

REWITNESS

I SET 2" IRON PIPE WITH 3" BRASS CAP IN 10" TILE & CEMENT @ POSITION OF FD. 1" I.P. SEE U.S. F.S. RE/WIT.

RESET FD U.S.F.S. METAL POST 28 FT. EAST



NEW ACCESSORY:

COMMENTS: THIS CORNER IS LOCATED IN ± CENTER OF A SMALL CREEK IN AN E.-W. CUTTING LINE AND ± 500 FT. WEST OF AN OLD LOGGING ROAD.

IN THE PRESENCE OF: GALE ARTHUR DAN McNUTT

DATE: 6-1-78

PHOTO#: REC: [Signature]

* = County corner tag affixed.

TITLE