Index File No. J-15

T 6S R. 10W

Merid. WILL.

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

I.D. HEBO County TILLAMOOK

I.F. SIUSLAW State OREGON

#993

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT ~~FOUND~~ GLO 1890 SET POST & MARKED

12" HEMLOCK, N. 37½° W., 3 3/ FEET.

10" HEMLOCK, S. 4½° E., 22 4/ FEET.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

FOUND 20" HEM., S. 4½° E., 22 4/ FEET. WITH HEALED WITNESS FACE.

FOUND 17" HEM., N. 37½° W., 3 3/ FEET WITH VISIBLE SCRIBING "¼ S".

PHOTO IDENTIFICATION DATA

Photo No. ETJ-6-219

Filed At. HEBO

Object Ident. DIRECT

Ident. By L. WHITMORE
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

SET ½" GALV. PIPE AT CORNER POINT WITH ALUMINUM POST ALONGSIDE WITH "PENALTY TO DESTROY SIGN ATTACHED.

PUT BEARING TREE SIGNS ON WITNESS TREES.

Signature	Title	Division	Headquarters	Date
Leonard Whitmore	Forestry tech	Timber	Hebo	7-20-71

7100-52 (3/

COWWE

REWITNESS

I SET _____

"x "x " Post N.W. feet

" Hat Section S. E.

NEW ACCESSORY:

COMMENTS: LEONARD WHITMORE IS A DEPUTY COUNTY SURVEYOR EMPOWERED TO SET WITNESS POSITIVE EVIDENCE OF [illegible] MONUMENTS.

IN THE PRESENCE OF:

DATE: _____ PHOTO#: _____

* = County corner tag affixed.

TITLE