


T65 R. 10W R.D. HeBo County TILLAMOOK G-17
 Will. N.F. SIU-SLAW State ORC USFS FILE



DESCRIBE CORNER MONUMENT FOUND
 FOUND A REMNANT OF THE ORIG. POST IN A ROTTED
 CONDITION. AT THE CORNER POINT I FOUND A
 STONE IMPLANTED BENEATH THE SURFACE OF THE
 GROUND. See Below # 994

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND 26" HEM., S. 25° E., 15² FT. WITH A SCRIBE
 MARK "S" SHOWING IN A PARTIAL HEALED FACE.
 FOUND THE S.W. BT LYING ACROSS A RAVINE IN A ROT-
 TED CONDITION.

IDENTIFICATION DATA
 ETJ-9-22 PHOTO
 HEBO FILED AT

SENT WITHIN 50 FT.
 L. WHITMARE
 Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 AT THE UPHILL SIDE OF THE STONE A REMNANT OF
 THE ORIG. POST IS FOUND EXTENDING 18" INTO THE GR-
 OUND.

COORDINATE POSITION DATA
 Zone

2-75 FOUND CORNER AND WITNESSES IN GOOD CONDITION.

SENT TO SO
 Agency

Signature Title Division Headquarters Date
 L. Whitmare Forestry Tech Timber Hebo 9-27-67
 7100-52 REV. 65

MONUMENT - DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

I SET A 3" X 3" SPRUCE LIMB MKD. SIC ON W. AND S.W. OR E. SIDES
 I MARK ONE NEW BT. Witnesses: N. Meane
 30" SPRUCE, N. 46° W., 30 FT. MKD. 1/4 S10 BT. G. Tilton
 Leonard Whitmare, Tilla Co. Dep. Surveyor

ACCESSORIES - DESCRIBE NEW BT.'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Leonard Whitmare is a Deputy County Surveyor empowered to re-identify
 positive identifiable found monuments in connection with his
 U.S.F.S. work - J. L. Carlisle
 12/79

Work Done By Title Date State Registration No. or Agency

Certified Copy Record Prepared? Yes No Filed At Date

REMARKS