

1. T. 6 S. R. 10 W. No. L-21 Cor. 7 Mer. Will State ORE (rectangular) N. F. SIUSSLAY Dist. YACBO

2. Corner Status

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: #999

14	13		

5. Investigation Notes:

FOUND 4"X4" WOOD POST 18 IN. ABOVE GROUND IN DECAYED CONDITION (NOT ORIG.)

FOUND 38 IN. SAWED OFF HEM. STUMP, S. 88° W., 22 LKS. WITH ROTTED VISIBLE MKS. $\frac{1}{4}$ S (ORIG.)

FOUND UPROOTED HEM. STUMP, N. 31° 30' E., 24 LKS. WITH WITNESS SCAR, DID NOT OPEN.

6. Signed L. WHITMORE Title FORESTRY TESH Date 9-27-62

7. Photo Identification
Photo No. _____
Ident. By: _____

8. Plane Coordinate Position Data
State _____ Zone _____
X _____
Y _____
Estab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation
Authentic _____
Needs Verif. _____ Monument _____
Re-estab. _____ Survey _____
Land Status PAT. - P. D.

Monuments

1. Accessories

EDWARD WHITMORE IS A DEPUTY COUNTY SURVEYOR EMPOWERED TO RE-WITNESS POSITIVE EVIDENCE OF ORIGINAL MONUMENTS J. C. 2/28/61

12. Set By _____ Title _____
Agency _____ Date _____

13. Recorded By _____ (Agency) _____ Volume _____ Page _____
(Date) _____ (City) _____ (County) _____ (State) _____

14. Remarks:

SET 1 1/2 IN. PIPE 2 FT. ABOVE GROUND.

NOTHING IS IN LIMITS IN SECTION 13 FOR WITNESS TREE

PUT BT SIGN ON THE ORIG WITNESS STUMP IN SECTION 14.

IN THE PRESENCE OF
E. D. GARDNER
JOHN ALLEN