

T 6 S R 10 W R.D. H.C.B.O. County TILLA - LINCOLN USFS #  
 Merid. Will N.F. Siuslaw State ORE. N-9a

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND GLO 1890. SET POST & MARK,  
 50" SNAG, N. 84° W., 29 LKS.  
 4" WILLOW, S. 72° E., 47 LKS. #1006

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND  
 M. WHITMORE, USFS, 3-18-57 FOUND ORIGINALS  
 AND REMAINS OF A STUMP N. 84° W., 29 LKS.  
 He MARKED 2 TREES; "  
 32" FIR, N. 79° E., 28 FT. T6SR10WS16 BT.  
 37" FIR, N. 60° W., 61 FT. "T6SR10WS17 BT."

PHOTO IDENTIFICATION DATA  
 Photo No. ET-5-160  
 Filed At. H.C.B.O.  
 Object Ident. DIRECT  
 Ident. By Leonard Whitmore  
 Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER  
 4-26-73 I FOUND ORIGINAL POST AND FOUND  
 2 FIRS WITNESSED BY M. WHITMORE.  
 I SET 1/2" IRON ROD ALONG SOUTH SIDE OF OLD POST

PLANE COORDINATE POSITION DATA  
 State Zone  
 COPY SENT TO SO Leonard Whitmore, USFS, 4-26-73  
 Estab. By Agency OK Kankin 12/79

Signature Title Date Headquarters  
 Leonard Whitmore Forestry Tech Forester Nelson 4-26-73 7100-52 (3)

U.S. Department of Agriculture  
 FOREST SERVICE  
 NATIONAL FOREST  
 CORNERS OF THE PUBLIC SURVEY  
 T. 6 S. R. 10 W. Will. Mer.  
 SEC. 30 R. 17, and 16  
 Corner common to Sections  
 Corner consists of a original post (set in place)  
 State condition PRAY

Dimensions above ground 30 inches.  
 Sketch grooves, letters, figures, or notches, on proper size scale.  
 STONE CORNERS METAL CORNERS

Sketch of old BT remains of stump.  
 Diameter 32" Fir  
 Bearing N. 79° E. N. 60° W.  
 Distance 29 LKS. 28 FT. 61 FT.  
 Do you believe this to be a genuine Land Office corner? YES  
 If not, why?

DATE: 3/18/59  
 Signature: Alexia Whitmore  
 Title: Forester  
 Form 574-9  
 Rev. Mar. 1953

\* = County corner tag affixed.