


T. 6 S R. 10 W R.D. HEBO County TILLA. - LINCOLN. USFS FILE
 Merid. Will. N.F. SIUSLAW State NEB. # N-9 B

CORNER DIAGRAM


DESCRIBE CORNER MONUMENT FOUND GLO 1905 SET POST & MKD;
12" ALDER, N. 5° E., 37 LKS.
8" ALDER, S. 83° W., 35 LKS. # 1012

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
M. WHITMORE, USFS, 3-18-59 FOUND ORIGINAL POST & IRON
PIPE.
THE N.E. ALDER HAD ROTTED OUT FACE.
HE SCRIBED 55" SPRUCE, N. 50° W., 23 FT. SCRIBED "T&W
520 FS BT." T&W

PHOTO IDENTIFICATION DATA
 Photo No. ETJ-5-160
 Filed At: HEBO
 Object Ident. DIRECT
 Ident. By L. Whitmore Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
4-26-73 I FOUND A 4" X 4" X 24" ORIGINAL POST W
TO A 1/2" GALV. PIPE. WIRED
FOUND 62" SPRUCE, N. 48° W., 22 FT. TO SIDE-CENTER W
HEALED WITNESS FACE. WITH
THE ORIG. N.E. ALDER IS DOWN.

PLANE COORDINATE POSITION DATA
 State NEB. Zone 18N

COPIES SENT TO SO
 Estab. By L. Whitmore Agency USFS

Analyst L. Whitmore Title Forestry Tech District Hebo Headquarters Hebo Date 4-26-73 7100-52 13

MONUMENT; DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Leonard Whitmore is a Deputy County Surveyor empowered to
 be witness positive, verifiable monuments found in connection
 with his USFS work

Martin C S 12/1/73

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At _____ Date _____

REMARKS
 ATTACH BT SIGN TO WITNESS TREE. PUT BOUNDARY TIN TO THE
 AND WEST.
 CORNER IS 20 FT. E. OF A BROOK RUNNING S. 37° W.

Leonard Whitmore, USFS, 4-26-73