

R. 16W	R.D. HEB0	County TILLAMOOK - LINCOLN	USFS FILE # N-11
WILL	N.F. STUSLAB	State ORC.	
DIAGRAM T6SR10W N-11 21	DESCRIBE CORNER MONUMENT GL01908 SET POST AND STONE MOUND. #1013 30' FIR, S. 80° W., 400 LKS. 30' FIR, S. 85° W., 450 LKS.		
DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND FOUND ORIGINAL POST WITH FAINT SCRIBE MARKS "1/4" ON SOUTH SIDE. POST IS IN ROCK MOUND WITH 1" PIPE ALONGSIDE.			
IDENTIFICATION DATA P. 673-5-160 (Photo) HEB0 (Filed at)			
DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER THE BT'S ARE GONE, APPARENTLY RAAGED BY THE MANY FIRES THAT HAVE SWEEP THROUGH THIS AREA			
COORDINATE POSITION DATA Zone SENT TO SO			
Agency			
Signature L. Whitmore	Title Forestry Tech	Decision Timber	Headquarters Hebo
		Date 4-26-73	52 (3/68)

REWITNESS

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING E

I SCRIBE 2 ALDERS;
14" ALDER, S. 72° W., 25 3/4 FT. SCRIBED IN BARK "1/4 S 21 BT."
12" ALDER, S. 1° E., 14 3/4 FT. SCRIBED IN BARK "1/4 S 21 BT."
VAR. 21" DISTANCES ARE TO SIDE-CENTER.

Leonard Whitmore, Tillamook County Deputy Surveyor, 4-26-73

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified, Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS
Leonard Whitmore is a Deputy County Surveyor empowered to re-witness positive, verifiable monuments found in connection with USFS work
Officer CS 12/1/79

Index File No T 65 R 10W M Tract or Surv. No. 21

DATE: _____ PHOTO: 2EC

County corner tag affixed. TILLAMOOK COUNTY COMMISSIONER TITLE