

USDA-FOREST SERVICE GPO 941 CORNER RECORD (SEARCH) Tract or Survey No. _____ Cor. No. _____
 (Ref. FSM 7151.4)

Index File No. M-13^B R.D. HEBO County TILLAMOOK-LINCOLN #1014
 T. 65 R. 10W N.F. SIUSLAW State ORE.

Merid. Will. DESCRIBE CORNER MONUMENT FOUND GLO 1905 SET CHERRY POST 4" MKD.
 CORNER DIAGRAM 24" Hem, S, 6°E, 48 LKS.
CLOSING CORNER 24" SPRUCE, WEST 17 LKS.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND 4" X 4" X 12" WOOD POST IN ROCK MOUND.
 FOUND 28" Hem, S, 12°E, 33 1/2 FT. WITH HEALED W. FACE. ^{Witness}
 FOUND 37" SPRUCE, N. 85°W, 12 FT. WITH HEALED WITNESS FACE.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____ Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
SET 1/2" IRON ROD ALONGSIDE POST IN ROCK MOUND.
NAIL BT SIGNS TO WITNESSES.

PLANE COORDINATE POSITION DATA
 State _____ Zone _____

COPY SENT TO SO

Signature: Leonard Whitmore, 4-73
 Date: _____

REWITNESS

I SET _____ "x" "x" " Post N.W. feet
 _____ " Hat Section S. E.

NEW ACCESSORY:

COMMENTS: _____

IN THE PRESENCE OF: _____

DATE: _____ PHOTO#: _____ TITLE _____

* = County corner tag affixed.