


CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

N-15
 6 S. R. 10W R.D. Heba County LINCOLN-TILLA #1015
 WILL N.F. SIUSLAW State OKE.

CORNER DIAGRAM
 PERTAINS TO NORTH BOUNDARY SEC. 22 ONLY


DESCRIBE CORNER MONUMENT FOUND @ L 1908 SET HEM. POST & MK
 18" HEM, S. 46° W.?, 37 LKS.
 16" HEM, S. 68° W.?, 16 LKS. MKD;

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 Post is gone,
 FOUND 20" HEM, S. 3° E, 10 1/2 FT. WITH VISIBLE SCRIBE MARKS IN ROTTED OPEN FACE.
 FOUND 22" DEAD HEM, STUB, S. 40° W, 24 1/2 FT. WITH VISIBLE SCRIBE MKS. "S 22 BT IN OPEN ROTTED FACE.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 COR. IS 4.35 CHS. W. OF 1/4 COR. FOR S. BOUNDARY OF SEC. 15.

PHOTO IDENTIFICATION DATA
 Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 X _____
 Y _____

Signature Leonard Whitmore Title Forestry Tech. Inspector Div. _____ Headquarters Heba Date 7-A-71 7100-52 (3)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
 Set 12x9x5 STONE AT COR. POINT & MARK. ~~12x9x5~~ " 1/4 " ON S. Side.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
 PUT BT SIGNS ON WITNESSES.

LEONARD WHITMORE IS A DEPUTY COUNTY SURVEYOR EMPLOYED TO RE-WITNESS & RE-MONUMENT POSITIVE IDENTIFICATION OF ORIGINAL CORNERS - OK

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____
 Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. 6 S. R. 10W. M. _____ Tract or Surv. No. _____ Cor. _____