

T 6 S R. 10 W R.D. HEBO County LINCOLN-TILLAMOOK
 Merid WILL. N=21 N.F. SIUSLAW State ORE.

CORNER DIAGRAM
 CLOSING CORNER

DESCRIBE CORNER MONUMENT ~~FOUND~~ GLO 1905 SET POST & MARK
10" ALDER, S. 44° E., 28 LKS.
18" ALDER, S. 86° W., 8 LKS. #1016 ED

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
FOUND 1 1/4" RUSTED GALV. PIPE BROKEN OFF AT
LEVEL. Ground

FOUND 27" ALDER, S. 86° W., 5 1/2 FT. WITH VISI
SCRIBE MARKS IN OPEN FACE. VISIBLE

PHOTO IDENTIFICATION DATA
 Photo No. ETJ-6-210
 Filed At: HEBO
 Object Ident. DIRECT
 Ident. By L. WHITMORE
 Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH C
THE S.E. ALDER BT IS MISSING.

PLANE COORDINATE POSITION DATA
 State _____ Zone _____
 Estab. By _____ Agency _____

State _____ Zone _____
COPY SENT TO SO

no. _____ Title _____ Di _____ Headquarters _____ Date 2-22-73 7100-52
Leonard Whitmore, Forestry Tech, Hebo

TITLE _____ TILLAMOOK COUNTY REGISTERED
 DATE: _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
SET 1/2" IRON ROD IN PIPE.
Leonard Whitmore is a Deputy County Surveyor employed by re-interview positive
identifiable monuments found in connection with his USFS work.
CORNER IS ON STEEP S.E. SLOPE. 12/79

ACCESSORIES: DESCRIBE NEW BT & WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE
I MARK A 10" CEDAR, S. 40° E., 9 FT. SCRIBED "T6SR10W S24 CC
ATTACH BT SIGNS ON WITNESS TREES. BT

Leonard Whitmore, Tillamook County Deputy Surveyor 2-22-73

Work Done By _____ Title _____ Date _____ State Registration No. _____
 or Agency _____

Certified Cor. Record Prepared Yes No Filed At: _____ Date _____

REWITNESS