


T. 6S R. 11W R.D. Hebo County TILLAMOOK  
 Merid. WILL. N.F. SUSLAW State ORE. USFS # G-21

CORNER DIAGRAM  


DESCRIBE CORNER MONUMENT FOUND GLG 1872 SET 14X12X12  
#1018 STONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND  
FOUND 12X10X9 STONE MARKED 1/4" ON West SIDE

PHOTO IDENTIFICATION DATA  
 Photo No. \_\_\_\_\_  
 Filed At \_\_\_\_\_  
 Object Ident. \_\_\_\_\_  
 Ident. By \_\_\_\_\_  
 Signature \_\_\_\_\_

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH  
OVER

PLANE COORDINATE POSITION DATA  
 State \_\_\_\_\_ Long. \_\_\_\_\_

**COPY SENT TO SO**

Exam. By \_\_\_\_\_

Inspector \_\_\_\_\_ Head Assessor \_\_\_\_\_ Date \_\_\_\_\_ 7103

ACCESSORIES DESCRIBE NEW BY'S WITNESS OBJECTS ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE  
I MARK 2 TREES; 84" SPRUCE, S. 80°W, 28 1/2 FT. SCRIBED "1/4 S11 CSB,  
VAR. 21" 20" HEM, N. 63°E, 39 FT. SCRIBED "1/4 S12 CSBT"  
Leonard Whitmore, Tillamook county deputy surveyor  
1-24-73

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. \_\_\_\_\_  
 or Agency \_\_\_\_\_

Certified Cor. Record Prepared? Yes  No  Filed At \_\_\_\_\_ Date \_\_\_\_\_

REMARKS  
CORNER IS LOCATED ON A SMALL BENCH.  
Leonard Whitmore is a Deputy County Surveyor empowered to set witness  
positive identifiable found monument in connection with his  
USFS work. All work in accordance with USFS rules.  
12/19 H-12

Tract or Surv. No. 6S R 11W 1/4

DATE: \_\_\_\_\_ TITLE \_\_\_\_\_

\* = County corner tag affixed.