


SEC 16 TWP 2N RGE 7W WM



MONUMENT AND ACCESSORIES

Set basalt stone, 18"x12"x7", 12" in ground, for cor. to secs. 16, 17, 20, & 21, mkd. with 4 notches on East and 3 on South edges, from which
 A Hemlock, 15" dia. N30 E. 15lks. mkd. "T2NR7WS16BT"
 A Hemlock, 10" dia. S40 E 73lks. mkd. "T2NR7WS21BT"

REFERENCE	DATE	FILED UNDER
A Hemlock, 20" dia. mkd. "T2NR7WS2DBT"	S85 W	33lks.
A Hemlock, 15" dia. mkd. "T2NR7WS17BT"	N47 W	65lks.
GLO	1893	Page 49

COMMENTS:

CORNER VISITS

MONUMENT/ACCESSORY*	LOCATION FROM CORNER	WITNESSES	DATE
At the site of the second temporary post, for the corner to sections 17, 16, 20, & 21, T2N, R7W, W.M., I set a 1 1/2" galvanized iron pipe 30" long 20" deep in loose soil and broken rock on steep hillside from which: A stump 40" dia., mkd. "S16BT" A stump 42" dia., mkd. "S17 T2N R7W 1957 BT" A stump 40" dia., mkd. "S20 322 BT" A stump 48" dia., mkd. "S21 BT"	N50 E 14.4' N44 1/2 W 102.4ft. S68 W 126.7ft. S31 1/2 E 80.4ft.	Bertell Mason Rob't L. McCullough	6/11/57
I found the galvanized iron pipe in good condition in loose soil and broken rock on steep hillside from which: A stump 40" dia. mkd. "S16BT" is now rotting with face badly weathered and scribes barely legible. A stump 42" dia., mkd. "S17 T2N R7W 1957 BT" is now a badly rotting stump with face and scribes badly weathered.	N50 E 14.4ft. N44 1/2 W 102.4ft.	G.A. Crites	5/4/81

*NOTE CONDITION AND ORIGIN.

CORNER VISITS

MONUMENT/ACCESSORY*	LOCATION FROM CORNER	WITNESSES	DATE
From the 1/4 corner between sections 16 & 17, T2N, R7W, W.M. I chain south by compass for the corner to sections 16, 17, 20 & 21, T2N, R7W, W.M. I place a temporary stake 129 ft. north of the brook, course E-W described in the original description, this being the nearest call.		Bertell Mason Jr.	6/6/57
From the temporary post I chain S80 E by compass for the 1/4 corner between sections 16 & 21, T2N, R7W, W.M. At 2975.5ft. I fall 65 ft. north of the corner.		Bertell Mason Jr.	6/10/57
From the temporary post I chain west on compass for the 1/4 corner between sections 17 & 20, T2N, R7W, W.M. At station 9 15 I find an old line blaze, reopened since the death of the tree, 26.5ft. south of my line. I fall 20 feet north and 56 feet east of the first two calls out of the temporary post. I don't find the 1/4 corner. I place a second temporary post 56 feet west and 26.5 feet south of my first post and chain south. I search along the line diligently for 1500 feet but fail to find any evidence of old line blazes.		Bertell Mason Jr.	6/11/57
Thirty feet east of the second temporary post I find a 16" Hemlock lying on its side with blazes on the east and west sides. It is impossible to find the spot from which this tree came. The blazes were made before the tree died, being partially grown over.			

*NOTE CONDITION AND ORIGIN

CORNER VISITS

MONUMENT/ACCESSORY*	LOCATION FROM CORNER	WITNESSES	DATE
A stump 40" dia., mkd. "S20 322 BT" is now a badly rotting stump with face and scribes legible but weathered	S68 W 126.7ft. (Mason set a Y.M.L.P. on this stump)		
A stump 48" dia., mkd. "S21 BT" is now a badly rotting stump with scribes legible but face badly weathered.	S31 1/2 E 80.4ft. (I set Y.M.L.P. and Y.M.B.T. tags on this stump)		

*NOTE CONDITION AND ORIGIN