CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 5, 6, 7, and 8 Township 1 South, Range 7 West, W.M., Tillamook County, Oregon

ORIGINAL Post, now missing, from which a:

8" Hemlock bears N 792E 51 lks.; now 7" down, BT and traces of other scribes visible.

7" Hemlock bears S39E 44 lks.; now 8" down, roots in place, Tl part of B and T scribes visible. 40" Hemlock bears S50W 38 lks.; now 61" stub 250 ft.

high, Tl BT scribes visible.

6" Hemlock bears N6W 24 lks.; now just roots remaining.

RESTORED

Set 12" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T1S R7W S5 S6 S7 S8 1954 RE 2311," 30 inches in ground, in mound of stone, and from which a:

67" Fir stump bears N302W 108.7 ft.; scribed T1S R7W S6 BT RE 2311.

78" Fir snag bears N47E 2000; scribed T1S R7W S5 BT

30" x 30" x 40" rounded sandstone boulder bears \$48E 31.8 Ft.; scribed BO. (Corner point is on west edge of 2 acre flat.)

Oregon State Board of Forestry metal location poster on 3" Fir N89E 29.8 ft. Set 4" x 4" x 72" White Cedar post 1.5 ft. NE of pipe. Also poster on 48" fir stump 594.0 ft. South of corner on ridge top.

Dated September 1, 1954

Restored by Amald & Sibyan under my direction Affold G. Gibson, Asst. Eng.

PREGON

10, 19A

Present and witnessed by Richard Morris, Robert Schumacher Lloyd Geraths

BookI