

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 8 and 17,  
Township 1 South, Range 6 West, Willamette  
Meridian, Tillamook and Washington Counties,  
Oregon.

ORIGINAL

Post, now missing, from which a:

- 30" Hemlock bears N36 $\frac{1}{2}$ °E 32 lks.; now 32" stub 15 ft. high portion of BT visible on old face.
- 24" Hemlock bears S79 $\frac{1}{2}$ °W 70 lks.; now 26" stub 20 ft. high, old face, scribes burnt off.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S8 S17 1954 RE 2311," 32 inches in ground, in small mound of stone, and from which a:

- 42" Fir stump bears N69°W 35.2 ft.; scribed 1/4 S8 BT RE 2311.
- 46" Fir stump bears S63°W 21.3 ft.; scribed 1/4 S17 BT.

Oregon State Board of Forestry metal location poster on original 42" Fir stub BT.  
4" x 4" x 72" white Cedar post 1.5 ft. SW of pipe.

Dated March 19, 1954.

Restored by Richard Morris under my direction.  
Richard Morris, Compassman



Present and witnessed by Alan Ramage

Book I