



CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 21 and 22,
T2N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

14"10"8" stone, now missing, from which a:

8" Hemlock bears S74°E 35 lks.; now 15", uprooted,
 $\frac{1}{4}$ " scribed visible, rest unexposed.

20" Hemlock bears S19°W 2 lks.; now 36" by 40" high
stub, $\frac{1}{4}$ " S scribes visible, rest unexposed.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ " S21 S22
1954 RE 2311," 30 inches in ground, in mound of
stone, and from which a:

12" Cedar bears N21°E 161.9 ft.; scribed $\frac{1}{4}$ " S22 BT.

32" Hemlock bears S2°W 60.1 ft.; scribed $\frac{1}{4}$ " S21 BT
RE 2311.


Oregon State Board of Forestry metal location poster on 12"
Cedar BT.

Oregon State Board of Forestry metal location poster on 36"
Hemlock stump 330 ft. N of corner on South edge log road.

Set 4"x4"x8" white Cedar post 3 ft. NE of pipe.

Dated December 8, 1954

Restored by Richard Morris under my direction.
Richard Morris, Engr. aide



Present and witnessed by Claude Weikel
Forest Logan
Lloyd Geraths