

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 27 and 34
T2N, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

14" x 10" x 8" stone in place, $\frac{1}{4}$ on N face (now badly
deteriorated) from which a:

34" Hemlock bears N24⁰W 8 lks.; now 36" 10 ft. high
stub badly rotted.

30" Hemlock bears S61⁰W 21 lks.; now 24" 8 ft. high
stub, partially uprooted and badly rotted.

RESTORED

Set 1 $\frac{1}{2}$ "x36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S27 S34 1954 RE 2311,"
34 inches in ground, and in mound of rock, with remains
of original stone on N edge of pipe, from which a:

29" Fir snag bears S81⁰E 63.0 ft.; scribed $\frac{1}{4}$ S34 BT
RE 2311.

53" Fir snag bears N59 $\frac{1}{2}$ ⁰E 73.6 ft.; scribed $\frac{1}{4}$ S27 BT.

Oregon State Board of Forest metal location poster on 29"
Fir snag BT.

Set 4"x4"x72" white Cedar post 1.5 ft. SW of pipe.

November 18, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Engr. Aide



Present and witnessed by Forest Logan
Lloyd Geraths
Claude Weikel