

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 16 and 21, T2N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

14"x13"x10" stone, found downhill out of place, 1/4 on face, from which a:

12" Hemlock bears N18°W 23 lks.; now 20" uproot, left face unexposed.

12" Hemlock bears South 17 lks.; now 25" stump, 1/4 scribes visible, BF face unexposed.

RESTORED

Set original stone in place with 1/4 on N face, and erected mound of rock around it, from which a:

19" Hemlock bears S14°E 80.0 ft.; scribed 1/4 S 21 BT RE 2311.

25" Hemlock bears N66°E 127.9 ft.; scribed 1/4 S16 BT.

Oregon State Board of Forestry metal location poster on 25" Hemlock BT.

Oregon State Board of Forestry metal location poster on 60" Fir stump on S edge log road 450 ft. N55°W.

Set 4"x4"x84" white Cedar post 1.5 ft. NW of stone.

Dated December 17, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Engr. Aide



Present and witnessed by Lloyd Geraths
Forest Logan