

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 18 and 19, T3N,
R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Stake, now missing, from which a:

- 40" Hemlock bears N61 3/4°E 36 1/2 lks.; root stubs remaining.
- 60" Fir bears S30 1/2°E 11 lks.; now 56" hollow stump, scribes
1/4 T remaining.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY 1/4 S18 S19 1955 RE2311," 33
inches in ground, in mound of stone, and from which a:

- 46" Fir stump bears N4 1/2°E 31.6 ft.; scribed 1/4 S18 BT RE2311.
- 49" Fir s tump bears S67°E 110.7 ft.; scribed 1/4 S19 BT.

Set 4"x4"x72" white painted Cedar post 1.5 ft. SE of pipe.
Oregon State Board of Forestry metal location poster on original
60" Fir stump BT.
Corner located on East bank road.

Dated June 6, 1955.

Restored by Richard Morris under my direction.
Richard Morris, Engineering Aide



Present and witnessed by Lloyd Geraths
Forrest Logan
Robert Sturm